B Program Start

At the first program start, you will be asked to:

- Set language and country
- · Set the serial interface
- Set company (name/logo)

The Help (User Manual) function requires that you have Adobe Acrobat Reader installed on your computer. For a free download, go to <u>www.Adobe.com</u>.

To access the Users Manual, go to ? > Help. Or, press the F1 key on the computer keyboard. The User Manual opens in the language for the selected setup.

C Set the serial interface

- 1. Install the software for the USB-IR Driver and connect the adapter cable. See separate instructions.
- In DMS software, select Settings > Serial Interface and then select the serial interface used for the data transmission from the test instrument in the "COM" input window.

For example, select COM 1 and click OK to confirm.

Fluke DMS 1.5 professional - Interface	
Select the serial PC interface on which the instrument is connected.	OK
Interface	Cancel

License Agreement

BY USING THIS SOFTWARE PRODUCT IN ANY MANNER, YOU ARE AGREEING TO ACCEPT THE FOLLOWING TERMS AND CONDITIONS.

Fluke Corporation (Fluke) grants you a non-exclusive right to use Fluke DMS Software (Product) on a single PC or workstation (node), or on multiple nodes, provided that a multi-use license is obtained from Fluke and the number of nodes does not exceed the number of nodes for which license fees are paid. This grant of license does not include the right to copy, modify, rent, lease, sell, transfer or distribute the Product or any portion thereof. You may not reverse engineer, decompile, or disassemble the Product.

Fluke warrants that the Product will perform in its intended environment substantially in accordance with the accompanying written materials for a period of 90 days from the date of license acceptance. Fluke does not warrant any downloading errors or that the Product will be error free or operate without interruption.

FLUKE DISCLAIMS ALL OTHER WARRANTIES, EITHER EXPRESS OR IMPLIED, BUT NOT LIMITED TO IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WITH RESPECT TO THE SOFTWARE AND THE ACCOMPANYING WRITTEN MATERIALS. In no event shall Fluke be liable for any damages whatsoever (including, without limitation, indirect, consequential, or incidental damages, damages for loss of business profits, business interruption, loss of business information, or other pecuniary loss) arising out of the use of or inability to use this Product, even if Fluke has been advised of the possibility of such damages.

Quick Start Guide



DMS Software

DMS COMP DMS COMP/PROF

Consult user documentation

- Go to www.fluke.com to register your product and find more information.
- To view, print, or download the latest manual or supplement, visit us.fluke.com/usen/support/manuals.

System Requirements

Processor	Pentium [®] 4 or higher with support of all customary operating systems
Operating system	Microsoft Windows [®] XP, Windows [®] 7, Windows [®] 8, Windows [®] 8.1, and Windows [®] 10
Memory	256 MB RAM
Hard drive memory	400 MB
Monitor	Super VGA (800 x 600).
Drive	CD-ROM/DVD
Input device	Mouse or compatible
Interface	RS-232 for data transmission. USB by means of optional adapter cable (USB - RS-232).

Image: State	_ 8 ×
Client Certificator/Test Dabibution current drauth BYD Sample Company Image: Company Image: Certificator/Test Dabibution current drauth Client Image: Company Image: Certificator/Test Dabibution current drauth Name: (End) Sample Company Image: Certificator/Test Pace Certificator/Test Client Name: (End) Sample Company Cert code: Pace Pace Pace Phone: (D123-56789-90) Cert code: Pace Pace Pace Pace State (D122-56789-90) Cert code: Pace Pace<	
Clent Cartificate/Test Disblaction current druit (Bit) Sample Company Image: Cartificate/Test Disblaction current druit Name: (Bit) Sample Company Image: Cartificate/Test Pathodate/Test Pathodate/Test Name: (Bit) Sample Company Image: Cartificate/Test Pathodate/Test Pathodate/Test Pathodate/Test Name: (Bit) Sample Company Clent code: Pathodate/Test Pathodate/Test Pathodate/Test Clent Mo: SA300 Remarks: Pemorstration data record Pemorstration data record Phone: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di123+56789-0 Pemorstration data record Pemorstration data record Sample custome: Di12-6678454 Pemorstration data record Pemorstration data record Sample custome: Di12-6678454 Pem	
IPO1 Sample Company Image: Company Site Image: Company Client Image: Company Name: (EM) Sample Company Client Name: (EM) Sample Company Contract: (FW) Merr Phone: 01224-55789-0 Model phone: 01224-55789-99 Email: Imfo@samplecustomer.xxx Company: Sample Company Sheet: 12 Cole Park	
Site Site Image: Company End tode: 400 Centati: SAX00 Remarks: 400 Centati: SAX00 Remarks: Demonstration data record Phone: D123+56789-0 Demonstration data record Mode phone: D123-56789-0 End tode: Fac: D123-56789-0 End tode: Demonstration data record Fac: D122-56789-0 End tode: End tode: Fac: D122-56789-0 End tode: End tode: Statistic: D123-56789-0 End tode: End tode: Fac: D122-56789-0 End tode: End tode: Statistic: D123-56789-0 End tode: End tode:	
Client Image: Concent y Name: (Br0 Sample Concent y) Clent No: SA300 Contact: Mr. Mile Phone: D1234-56790-0 Mobile phone: D1204-0 Mobile phone: D1204-0 Mobile phone: D1204-0 Mobile phone: D1204-0	
Client Remarks: Otert Nov: SAX0 Contact: Mole phone: Plane: 0123-956789-0 Mole phone: 0123-956789-0 France: 0123-956789-0 Email: Info@sample.customer.xox Coparty: Sample customer Street: 12 Ouk Park	
Client EP/ Sample Company Client code: #00 Client Noi: SAX00 Remarks: #00 Contact: VP- Miler Phone: Di234-56789-0 Mode phone: Di234-56789-0 Emonstration data record Mode phone: Di234-56789-0 Emonstration data record Fax: Di234-56789-0 Emonstration data record Statistic Statistic Company: Statistic Company: Statistic Statistic Company: Statistic Company: Street: 12 Cole Park Emonstration data record	
Citent Name: B/0 Sample Company Citent code: #00 Clent Na: SA300 Remarks: #00 Contact: Mr. Mile Percentation data record Phone: D1234-56790-00 Percentation data record Mobile phone: D1234-56790-91 Percentation data record Email: Mr. B/B sample.customer.xxx Percentation data record Company: Sande customer Percentation data record Location: Info Basen/Percentation Percentation data record	
Name: (Br) Sample Company Clent Kode: #00 Clent Moi: SA300 Remarks: Performance Plane: D122-95789-0 Performance Performance Model phone: D123-9578-93 Performance Performance Fax: D123-9578-93 Performance Performance Email: Info@samplecustomer.xxx Performance Performance Street: 12 Calk Park Performance Performance	
Glent Nei SA300 Remarks: Demonstration data record Contact: M- Miler Private: Disases 578 90 Mobile channe: Di324 5678 90 Private: Disases 578 90 Mobile channe: Di329 5678 90 Private: Disases 578 90 Fac: Di329 5678 90 Private: Disases 578 90 Fac: Di329 5678 90 Private: Disases 578 90 Glent Neissen: Inflogrampfoculture::xxxx Private: Disases 578 90 Company: Sample customer: Disases 578 90 Private: Street: 12 Osk Park Disases 578 90 Private:	
Contact: P6, Miler Phone: 01224-56789-0 Mobile phone: 01224-56789-9 Fas: 01224-56789-99 Email: nt/ogeample.customer.xxx Company: Sample.customer Street: 12 Cak Park	
Phone: 0.123-65789-0 Mobile phone: 0.123-9678543 Fanc: 0.123-65789-9 Email: prior@sample.ustomer.xxx Company: Sample.ustomer Location: I Street: 112 Cak Park	
Mode phone: 0123-9575-03 Fac: 01223-5579-99-9 Email: onfo@sample.cutomer.xxx Company: Sample cutomer Street: 12 Calk Park	
Fac: 0:22+56789.99 Email: Info@samplecutomer.xxx Company: Sample cutomer Location: Info@samplecutomer.xxx Street: 12 Oak Park	
Email: Info@Bamplecuttome.xxx Company: Sample cuttomer Location: Info@Bamplecuttomer Street: I2 Cok Park	
Company: Sample customer Location: I2 Dak-Park	
Location: Street: 12 Oak Park	
Street: 12 Oak Park	
Post code: 12345	
Oty: Any Place	

Kit Contents

- DVD with Fluke DMS Software (includes Users Manual)
- Quick Start Guide
- IR-USB interface cable for use with 0100/INST
- USB cable for use with 0702/PAT
- Mini CD with USB-IR Driver
- USB Cable Installation Guide

A Software Installation

A Caution

Before the installation of the Fluke DMS software, restart Windows or end all running application programs (also programs working in the background, such as virus scanners).

1. Insert the DVD into the computer drive.

The SETUP.EXE program starts automatically when the CD-ROM is inserted.

If the program does not start automatically, start Windows Explorer and select the DVD drive. Select the SETUP.EXE file with Explorer. Double-click to start the installation.

2. At the prompt, select the installation language (English, German, French, or Dutch).

The sub-folders DATA and BACKUP are created in the installation folder. The database FDMSPRO1x.MDB is in the DATA sub-folder. The transmission protocols are also in the DATA folder.

3. Use Settings > Directories to set up the DATA folder.

If this folder is not set up, the application uses the DATA sub-folder. Data is backed up in the BACKUP sub-folder. All backup copies of the transmission protocols and the backup of the database are saved to this folder. If no folder is entered, the application uses the BACKUP sub-folder.

The Access Run Time Module must be installed on your computer. Supported versions are Access 2002 Run Time, Access 2003 Run Time, Access 2007 Run Time, and Access 2010 Run Time. The recommended version is Access 2010 Run Time. You can install Access 2010 Run Time when you install DMS.

If you choose to install Access 2010 Run Time, click Close when the DMS Software installation is complete. The corresponding language version installs and the context menus and error messages show in this language. Depending on the Operating System, you may also be asked to restart the computer after the installation of Access 2010 Run Time is complete.