

Instruction Sheet


PN 1700736

July 2011/RevA

CSA pH Sensor Hazardous Area Installation

CSA Installation Drawing

CSA Certificate of Compliance: 2389070 (LR 034186)



The pH sensors listed below can be used with this installation drawing. Sensors may or may not contain an integral preamplifier.

- | | | |
|-----------|---------|----------|
| 3900/VP | 396/VP | 399/VP |
| 3500/VP | 396R/VP | 389/VP |
| 3300HT/VP | 396P/VP | 385/385+ |
| 3400HT/VP | 398R/VP | |

Sample Labels

WARNING
EXPLOSION HAZARD
 ELECTROSTATIC
 Only clean with damp cloth.

Pressurized spray injury

Assembled in Mexico
 Model#3500-PR-02-10-21-30
 RTD Pt100 Soft. Ver. _____
 SQ#10123 SO#81000123
 SN:B10-1245078-002
 A/M 3500P-PR-02-10-21-30-

(BAR CODE)

ROSEMOUNT[®]
 Analytical Irvine, CA, USA

IS I,II,III, 1, ABCDEFG
 T6 Tamb=60°C See manual.

BAS: 9241722-00/A
 CSA: 9241723-00/A
 FM: 9241724-00/A

① Information from other agencies may appear on this label.
 ② These are data fields; information may vary from what is shown.

TITLE		
LABEL, INFORMATION, SENSOR, CSA		
SIZE	DWG NO	REV
B	9241723-00	A
SCALE: NONE	WEIGHT:	SHEET 1 OF 1

extracted from drawing 9241723-00

ROSEMOUNT[®]
 Analytical

MODEL _____ to 105°C (140°C)
 SN _____ 6 barg

IS I,II,III, 1, ABCDEFG
 T6 Tamb=60°C See manual.

(BAR CODE) Made in USA

① Information from other agencies may appear on this label.

TITLE		
LABEL, SENSOR 3800/3800VP, CSA		
SIZE	DWG NO	REV
B	9241727-00	A
SCALE: 1:1	WEIGHT:	SHEET 1 OF 1

extracted from drawing 9241727-00

Emerson Process Management

2400 Barranca Parkway
 Irvine, CA 92606 USA
 Tel: (949) 757-8500
 Fax: (949) 474-7250

<http://www.raihome.com>